

AD-A078 898

GAI CONSULTANTS INC MONROEVILLE PA  
NATIONAL DAM INSPECTION PROGRAM. GALLO DAM (NDS  
SEP 79

F/G 13/13  
I.D. NUMBER PA---ETC(U)  
DACW31-79-C-0013


NL

UNCLASSIFIED

1 OF 1

AD  
A078898





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



AD A 078898

OHIO RIVER BASIN  
BEAVERDAM RUN, SOMERSET COUNTY


PENNSYLVANIA  
GALLO DAM

LEVEL #

NDS I.D. No. PA - 00233  
PENNDER I.D. No. 56 - 91

SC

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE  
PREPARED FOR

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0013


DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

PREPARED BY

GAI CONSULTANTS, INC.  
570 BEATTY ROAD  
MONROEVILLE, PENNSYLVANIA 15146

SEPTEMBER 1979

DDC FILE COPY



30 - 7 1 055

## **DISCLAIMER NOTICE**

1

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

(12) 91

(11) Sep 79

PREFACE

(15) DACW31-79-C-0013

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

(6) National Dam Inspection Program.  
Gallo Dam (NDS I.D. Number  
PA-00233, Pennder I.D. Number  
56-91) Ohio River Basin,  
Beaverdam Run, Somerset  
County, Pennsylvania.  
Phase I Inspection Report.

Accession For	
Serial	1
Doc. No.	
Form used	
Classification	
Availability Codes	
Avail and/or	special
Disc.	
411 002 2m A 33	



PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Gallo Dam: NDI I.D. No. PA-00233

<u>Owner:</u>	John Gallo
<u>State Located:</u>	Pennsylvania (PennDER I.D. No. 56-91)
<u>County Located:</u>	Somerset
<u>Stream:</u>	Beaverdam Run
<u>Inspection Date:</u>	6 August 1979
<u>Inspection Team:</u>	GAI Consultants, Inc. 570 Beatty Road Monroeville, PA 15146

Based on the visual inspection, operational history, and available engineering data, the dam is considered to be in fair condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for this facility is the Probable Maximum Flood (PMF). Results of the hydrologic and hydraulic analysis indicate that the facility is capable of passing and/or storing only about 13 percent of the PMF prior to overtopping of the embankment. Overtopping and embankment failure is anticipated under floods of less than 1/2 PMF magnitude and would result in an increase in the potential for loss of life downstream from the dam. Thus, based on criteria contained in the recommended guidelines, the spillway is considered to be seriously inadequate.

Deficiencies noted during the investigation include a densely overgrown and brush-strewn downstream dam face; erosion ditches cut into the irregular downstream face; saturated embankment conditions in the vicinity of the low level outlet from the dam toe to a point 13 feet below the dam crest; poor drainage conditions immediately downstream of the embankment toe; and rotation of the concrete cap portion of the spillway weir.

Due to the seriously inadequate spillway classification, the facility is considered unsafe, but non-emergency as failure

is not considered imminent. However, it is recommended that the owner immediately develop a warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

In addition, it is recommended that the owner:

a. Have the facility studied by a registered professional engineer experienced in the hydraulics and hydrology of dams, and implement the measures necessary to make the facility hydraulically adequate.

b. Cut the overgrowth and clear all brush from along the downstream embankment slope and toe to permit detailed inspection of the facility.

c. Have the facility inspected by a registered professional engineer experienced in the design and construction of earth dams to assess the stability of the embankment, particularly in the vicinity of the observed saturation near the siphon, and take necessary remedial measures as recommended.

d. Provide positive controlled drainage of the flow observed along the abutment-embankment contact and immediately downstream of the toe area to eliminate the ponding and swamp-like conditions.

e. Regrade and seed the embankment crest and downstream slope to eliminate concentrated runoff and erosion ditches, and provide a smooth surface amenable to maintenance and inspection.

f. Provide a means whereby the low level outlet pipe can be closed, as well as opened, on its upstream side, at all times.

g. Develop formal manuals to ensure continued care, maintenance, and proper operation of the facility.

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin James W. Sech  
Bernard M. Mihalcin, P. E.



Date 18 SEPT 1979

Date 25 Sep 79





OVERVIEW PHOTOGRAPH

## TABLE OF CONTENTS

	<u>Page</u>
PREFACE . . . . .	i
ABSTRACT. . . . .	ii
OVERVIEW PHOTOGRAPH . . . . .	v
TABLE OF CONTENTS . . . . .	vi
SECTION 1 - GENERAL INFORMATION . . . . .	1
1.0 Authority . . . . .	1
1.1 Purpose . . . . .	1
1.2 Description of Project. . . . .	1
1.3 Pertinent Data. . . . .	2
SECTION 2 - ENGINEERING DATA. . . . .	6
2.1 Design. . . . .	6
2.2 Construction Records. . . . .	7
2.3 Operational Records . . . . .	7
2.4 Other Investigation . . . . .	7
2.5 Evaluation. . . . .	7
SECTION 3 - VISUAL INSPECTION . . . . .	9
3.1 Observations. . . . .	9
3.2 Evaluation. . . . .	10
SECTION 4 - OPERATIONAL PROCEDURES . . . . .	11
4.1 Normal Operating Procedure. . . . .	11
4.2 Maintenance of Dam. . . . .	11
4.3 Maintenance of Operating Facilities . . . . .	11
4.4 Warning System. . . . .	11
4.5 Evaluation. . . . .	11
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION . . . . .	12
5.1 Design Data . . . . .	12
5.2 Experience Data . . . . .	12
5.3 Visual Observations . . . . .	12
5.4 Method of Analysis. . . . .	12
5.5 Summary of Analysis . . . . .	12
5.6 Spillway Adequacy . . . . .	14
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY. . . . .	15
6.1 Visual Observations . . . . .	15
6.2 Design and Construction Techniques. . . . .	15
6.3 Past Performance. . . . .	16
6.4 Seismic Stability . . . . .	16
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES . . . . .	17
7.1 Dam Assessment. . . . .	17
7.2 Recommendations/Remedial Measures . . . . .	17



## TABLE OF CONTENTS

APPENDIX A - CHECK LIST - ENGINEERING DATA
APPENDIX B - CHECK LIST VISUAL INSPECTION
APPENDIX C - HYDROLOGY AND HYDRAULICS
APPENDIX D - PHOTOGRAPHS
APPENDIX E - GEOLOGY
APPENDIX F - FIGURES
APPENDIX G - REGIONAL VICINITY AND WATERSHED BOUNDARY MAP

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
GALLO DAM  
NDI # PA-233, PENNDER # 56-91

SECTION 1  
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Gallo Dam is a 29-foot high earth embankment approximately 690 feet long (including spillway). The embankment is reportedly comprised of 3 sections which include an impervious core, a semi-pervious upstream section and a pervious downstream section. (see Figure 3).

The facility is served by a chute channel spillway, with discharges controlled by a free overfall, concrete weir structure. The spillway is located near the right abutment, and has a crest length of 39 feet. In addition, the facility is equipped with a 18-inch diameter steel pipe encased in concrete used as a low level outlet as well as a 16-inch diameter steel siphon (see Photograph 2) which was installed in 1973.

b. Location. Gallo Dam is located on Beaverdam Run in Jenner Township, Somerset County, Pennsylvania. The dam, reservoir, and watershed are contained within the Boswell and Ligonier, Pennsylvania 7.5 minute U.S.G.S. topographic quadrangles (See Appendix G). The coordinates of the dam are N40° 8.8' and W79° 5.8'.

c. Size Classification. Small (29 feet high, 440 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (See Section 3.1.e.).

e. Ownership. John Gallo  
c/o Ligonier Valley Beach  
Lincoln Highway East  
Ligonier, PA 15658 .

f. Purpose. Recreation (Commercial development).

g. Historical Data. Information available in PennDER files indicates that the facility was designed by the Neilan Engineers of Somerset, Pennsylvania and constructed by the Latrobe Construction Company. The facility was completed in 1958.

The field inspection indicated several discrepancies relative to the available drawings, including the orientation of the spillway, the relative freeboard between the original weir crest and the top of the dam, and the character of the outlet system. Correspondence in PennDER files indicates that, although the Neilan Engineers designed the facility, they did not provide construction inspection. In addition to the changes that were made during construction, several post-construction changes were made which included the raising the spillway crest and sidewalls in 1969, the addition of a 16-inch diameter steel siphon in 1973, and the placement of additional fill on the embankment in 1974.

### 1.3 Pertinent Data

a. Drainage Area (square miles). 3.8

b. Discharge at Dam Site.

Discharge Capacity of the Outlet Conduits-Discharge curves are not available.

Discharge Capacity of the Spillway at Maximum Pool  
≈ 730 cfs.

c. Elevation (feet above mean sea level). The following elevations were obtained from available drawings and through field measurements which were based on the elevation of the downstream toe of the spillway weir at 1843.5 feet.

Top of Dam	1853 (design) 1850.5 (field)
Maximum Design Pool	Not known
Maximum Pool of Record	Not known
Normal Pool	1847.3
Spillway Crest	1847.3



	Upstream Inlet Invert	1833
	Downstream Outlet Invert	1822
	Streambed at Dam Centerline	1822
	Maximum Tailwater	Not known
d.	<u>Reservoir Length (feet).</u>	
	Top of Dam	3100
	Normal Pool	3000
e.	<u>Storage (acre-feet).</u>	
	Top of Dam	440
	Normal Pool	330
	Design Surcharge	Not known
f.	<u>Reservoir Surface (acres).</u>	
	Top of Dam	36
	Normal Pool	33
	Maximum Design Pool	Not known
g.	<u>Dam.</u>	
	Type	Zoned Earth.
	Length	690 feet (field measured; including spillway).
	Height	29 feet (field measured; embankment crest to invert at outlet conduit).
	Top Width	30 feet (field measured).
	Upstream Slope	2H:1V
	Downstream Slope	1-1/2H:1V (irregular and varies locally).
	Zoning	Impervious core with a semi-pervious upstream shell and a pervious downstream shell.

Impervious Core	Impervious material reportedly placed in thin lifts and compacted.
Cutoff	A cutoff trench about 5 feet deep and 10 feet wide reportedly exists beneath the impervious clay core.
Grout Curtain	None indicated.
h. <u>Diversion Canal and Regulating Tunnels.</u>	None.
i. <u>Spillway.</u>	
Type	Concrete chute channel with discharges controlled by a concrete weir structure; located near right abutment.
Crest Elevation	1847.3
Crest Length	39 feet
j. <u>Outlet Works.</u>	
Low Level Outlet	18-inch diameter steel low level outlet pipe (blowoff) encased in concrete (See Figure 4. Note: Inlet riser was not constructed as shown).
Siphon	16-inch diameter steel siphon; can be used to lower the water level to 6 feet below normal pool level.

Conduit Lengths

Blowoff - 108 feet  
(estimated)  
Siphon - 150 feet  
(estimated)

Closure and Regulating  
Facilities

Low level outlet has  
concrete plug (lid)  
on short riser on  
upstream side. A  
galvanized steel cable  
(attached to lid and  
dam crest) is pulled  
to lift plug and drain  
reservoir.

Access

Galvanized steel cable  
is attached to crest  
of dam. Gate valve  
on siphon is accessible  
from downstream face  
of dam.



## SECTION 2 ENGINEERING DATA

### 2.1 Design.

a. Design Data Availability and Sources. No design reports or calculations are available concerning any aspect of this facility. Design drawings were obtained from PennDER files, although field inspection notes indicate that they are not as-builts. Correspondence and permit application reports obtained within PennDER files contain few design references and details, and indicate that no formal construction specifications were prepared. Soil placement and compaction criteria were, however, amended to the construction permit.

#### b. Design Features.

1. Embankment. Information contained within PennDER files indicates that the structure was designed as a zoned earth embankment with an impervious core, a semi-pervious upstream shell, and a pervious downstream shell (See Figure 3). The upstream face was mantled with sandstone riprap from 4 feet below normal pool up to the dam crest. The downstream face was covered with 4 inches of topsoil and seeded. Both upstream and downstream slopes were set at 2H:1V.

Little information is available relative to the embankment foundation, except that a cutoff trench about 5 feet deep and 10 feet wide was to have been constructed beneath the impervious core section of the embankment.

#### 2. Appurtenant Structures.

a) Spillway. The spillway was to be a concrete chute channel with discharges controlled by a concrete trapezoidal-shaped weir structure located near the right abutment. The weir crest was to be approximately 40 feet long, with the weir flanked by concrete wingwalls which were to rise about 8 feet above the weir crest. However, field measurements indicate that only about a 5.5-foot freeboard was provided for the spillway. Modifications were made to the spillway in 1969, resulting in the raising of the crest and sidewalls to their present configuration. The spillway sidewalls were not raised an equal height with the spillway crest, resulting in a further reduction of the design spillway capacity.

b) Outlet Works. Information contained on design drawings indicates that the facility was to be provided with a low level outlet and a vertical concrete riser which would serve as the primary spillway. Apparently, however,

these plans were modified, and the dam is provided only with the low level outlet conduit which is capped with a concrete lid attached to a galvanized steel cable. The cable is secured to the dam crest, and reportedly can simply be pulled in order to drain the reservoir.

A 16-inch diameter steel siphon was added to the facility in 1973. The siphon can be used to lower the water level to approximately 6 feet below the spillway crest.

c. Design Data and Procedures.

1. Embankment. No design data or information relative to design procedures are available.

2. Appurtenant Structures. No design data or information relative to design procedures are available, with the exception of a reference in PennDER correspondence which recommends designing the spillway to pass a flow of 900 cfs per square mile. Numerous discrepancies exist between the design drawings and the as-built conditions.

2.2 Construction Records.

No records pertaining to the construction of the facility are available. In addition, no records of the modifications exist.

2.3 Operational Records.

No pool level, rainfall or spillway discharge records are available for the facility

2.4 Other Investigations.

Two PennDER inspection reports, dated November 25, 1958 and May 2, 1963, indicate that the conditions at the dam were satisfactory.

2.5 Evaluation.

Little information is available relative to design parameters. Some modifications made during construction include:

1. Change in the inclination of the spillway with respect to the dam axis as shown on design drawing (Figure 2).
2. Deletion of the concrete riser which was to function as the primary spillway.

In addition to the as-built changes, several post-construction changes were made to the facility which affect its performance. They include:



1. The re-shaping and raising of the weir crest by approximately two feet, although the sidewalls were only raised about six inches.

2. The addition of a 16-inch diameter steel siphon which enables the owner to lower the pool level without completely draining the facility.

3. The placement of additional material along the dam crest in 1974.

The available data, although limited, are considered sufficient to make a general Phase I assessment of the facility.

## SECTION 3 VISUAL INSPECTION

### 3.1 Observations.

a. General. The general appearance of the facility suggests that it is in fair condition.

b. Embankment. Observations made during the visual inspection indicate the embankment to be in fair condition. Deficiencies include a heavily overgrown and brush-strewn downstream face, an uneven downstream slope with erosion ditches at several locations (See Figure 1), and swamp-like conditions immediately downstream of the embankment toe.

In addition, the downstream face of the embankment is saturated above the low level outlet conduit, from the dam toe to a point about 13 feet below the dam crest.

c. Appurtenant Structures.

1. Spillway. The visual inspection indicated that the spillway is in fair condition. Much of the concrete surfaces exhibit scaling, and the wingwalls contain hairline cracks and efflorescence (See Photos 1 and 3).

A portion of the lower end of the spillway was dislodged in the past, necessitating some remedial work (See Photograph 4). Also, the weir crest was re-shaped and raised in 1969 by approximately 2 feet, while approximately 6 inches of concrete was added to the spillway weir sidewalls (See Photograph 3). The modification has resulted in the reduction of spillway capacity. The spillway crest addition is cracked and somewhat rotated (See Photograph 3), possibly from ice pressure.

2. Outlet Works. The outlet works at Gallo Dam is somewhat unconventional in that, to drain the reservoir, a galvanized steel cable connected to a concrete lid on the upstream side of an 18-inch diameter concrete-encased steel pipe is pulled, essentially pulling the plug on the reservoir. A new cable was reportedly installed in 1978.

A second outlet, a 16-inch diameter steel siphon, was functioning at the time of inspection, and can be used to lower the water level to approximately six feet below normal pool level. The siphon basically operates as a low flow service spillway.

d. Reservoir Area. The terrain surrounding the reservoir is moderately to steeply sloped and lightly forested. No signs of slope distress were observed.

e. Downstream Channel. The downstream channel is confined within a relatively gently sloped and broad floodplain for about 9000 feet to Beaverdam Run's confluence with the North Branch of Quemahoning Creek. No dwellings or structures are located within this reach. In the next 4000 feet, the floodplain broadens and the North Branch of Quemahoning Creek combines with Quemahoning Creek. Several coal processing and/or related structures are located within this portion of the floodplain. These structures could suffer damage from the large flows which should be associated with a breach of Gallo Dam. Approximately 8000 feet further downstream, Quemahoning Creek passes under U. S. Route 30 in the community of Ferrellton. A commercial establishment and three mobile homes are situated sufficiently close to the stream such that large flows could cause significant damage to the dwellings (estimated population 10 to 20). Therefore, the hazard classification of Gallo Dam is considered to be high.

### 3.2 Evaluation.

The overall condition of the facility is considered to be fair. Deficiencies noted during the inspection included a dense overgrowth and brush-strewn downstream dam face; an irregular downstream face, with erosion ditches cut into the embankment at several locations; and a saturated zone above the low level outlet pipe, from 13 feet below the dam crest to the dam toe. The spillway appears to be in fair condition; however, modifications to the weir crest have reduced its capacity. A siphon pipe has been added to the facility, presumably to provide low flow discharge capacity, and drawdown capability without fully draining the facility.



SECTION 4  
OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

The facility is basically self-regulating. Excess inflow passes over the concrete weir structure, into the chute channel, and finally discharges into Beaverdam Run. Discharge at low pool level can be passed through a siphon pipe which is controlled via a gate valve located near the dam toe.

4.2 Maintenance of Dam.

No formal maintenance program exists at the facility. Maintenance is performed on an unscheduled basis. Rock is stockpiled at several locations on the dam crest and is used for riprap replacement when necessary. Trees were cut on the downstream face in 1979, but were not removed and hindered the visual inspection.

4.3 Maintenance of Operating Facilities.

See Section 4.2 above.

4.4 Warning System.

No warning system is in effect at this time.

4.5 Evaluation.

No formal operations or maintenance manuals are available for the facility, and no formal warning system exists. Formal manuals are recommended to ensure continued maintenance and safety.

## SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

### 5.1 Design Data.

No hydrologic/hydraulic design data or calculations are available with respect to the original or modified spillway systems.

### 5.2 Experience Data.

No daily records are available; but, the owner reports that the maximum spillway discharge has been approximately 14 inches to 16 inches over the existing weir.

### 5.3 Visual Observations.

Based on the visual inspection, the spillway is in fair condition. The weir cap is cracked and slightly misaligned; however, failure of the cap would not produce any significant consequences. The failure of the downstream edge of the spillway (probably from undercutting) appears to have been adequately repaired. No major deficiencies were observed that would indicate the spillway could not perform satisfactorily, within the limits of its design capacity, during a flood event.

### 5.4 Method of Analysis.

The facility has been analyzed in accordance with the procedures and guidelines established by the U.S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U.S. Army Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix C.

### 5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Gallo Dam ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. The classification is based on the relative size (small), and the potential hazard of dam failure to downstream developments (high). Due to the high potential for downstream damage, and to the relatively large storage volume behind the dam at maximum pool (about 440 acre-feet), the SDF for this facility is considered to be in the PMF.

b. Results of Analysis. Gallo Dam was evaluated under near normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of approximately 1847.3 feet, with all low level outlets assumed to be closed, and the spillway discharging freely. The spillway is a concrete chute channel, with discharges controlled by a concrete weir structure. The necessary downstream channel routing was done under the assumption that the routing stream was dry prior to the inflow of the dam outflow. Only the potential storage available along the main watercourse was considered in the routing computations. A more detailed study might consider the potential storage capabilities of the various tributary streams, since the stream gradients are quite gentle. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix C.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Gallo Dam can accommodate only about 13 percent of the PMF (SDF) prior to the overtopping of the embankment (Appendix C, Summary Input/Output Sheets, Sheet J). The low top of the dam was inundated by depths of water of 1.7 and 3.1 feet under the 1/2 PMF and PMF events, respectively (Summary Input/Output Sheets, Sheet J). Therefore, since the SDF for this facility is the PMF, Gallo Dam has a high potential for overtopping, and thus, for breaching under floods of less than SDF magnitude.

Since Gallo Dam cannot safely handle a flood of at least 1/2 PMF magnitude, the possibility of embankment failure under floods of 1/2 PMF intensity or less was investigated (in accordance with ETL-1110-2-234). Several feasible alternatives were analyzed since it is difficult, if not impossible, to determine exactly how or if a specific dam will fail. The major concern of the breaching evaluations is with the impact of the various breach discharges on increasing downstream water surface elevations above those to be expected if breaching did not occur.

The Modified HEC-1 Computer Program was used for the breaching analysis with the assumption that the breaching of an earth dam would begin once its reservoir's water level reached the low top of dam elevation.

Two sets of breach geometry were evaluated for Gallo Dam for each of two failure times (Appendix C, Sheet 18). The two sets of breach sections chosen were considered to be the minimum and maximum probable failure sections. The two failure times (total time for each breach section to reach its final dimensions), under which the two breach sections were investigated, were assumed to be a rapid time (0.5 hours) and a prolonged time (4.0 hours), so that a range of this most sensitive variable might be examined.



In addition, an average or more probable set of breach conditions was analyzed, with a failure time of 2.0 hours.

The peak breach outflows (resulting from a 0.15 PMF overtopping) ranged from about 2540 cfs for the minimum section-maximum fail time scheme to about 20090 cfs for the maximum section-minimum fail time scheme (Appendix C, Sheet 20). The outflow from the average breach scheme was about 5720 cfs, compared to the non-breach 0.15 PMF peak outflow of about 860 cfs (Summary Input/Output Sheets, Sheets M and J). The water surface elevation corresponding to the non-breach 0.15 PMF peak discharge at the section (Section 6) located about 15600 feet downstream from the dam was approximately 1811.5 feet (MSL); and approximately 1802.1 feet (MSL) at a section (Section 8) located about 21050 feet downstream from the dam (Summary Input/Output Sheets, Sheet K). The water surface elevations corresponding to the average breach conditions peak outflows at the two above-mentioned downstream sections were 1815.7 feet (MSL) and 1807.7 feet (MSL), respectively (Summary Input/Output Sheets, Sheet P). The approximate elevation of the residence located at Section 6 is about 1820 feet (MSL); while the approximate elevation of the residences and businesses located at Section 8 is about 1806 feet (MSL). Therefore, the increase in the water surface at Section 6, caused by the failure of Gallo Dam, was about 4.2 feet, with the breach water surface well below the dam level of the residence. The increase in the water surface at Section 8, caused by the failure of the dam, was about 5.6 feet, with the breach water surface above the damage level of the structures. It can further be surmised that embankment failure under somewhat larger base flood conditions could possibly cause damage to the residence at Section 6.

The consequences of dam failure can be better envisioned if not only the increase in the height of the floodwave is considered, but also the great increase in the momentum of the larger and probably swifter moving volume of water. Therefore, the failure of Gallo Dam is quite possible, and will most probably lead to increased property damage and possibly to increased loss of life in the downstream regions.

#### 5.6 Spillway Adequacy.

As presented previously, under existing conditions, Gallo Dam can accommodate only about 13 percent of the PMF (SDF) prior to embankment overtopping. Should a 0.15 PMF or larger event occur, the dam would be overtopped and could possibly fail, endangering the residences and increasing the potential for loss of life in the downstream regions. Therefore, the spillway is considered to be seriously inadequate.

SECTION 6  
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment appeared to be in fair condition. Several deficiencies were noted which will require the owner's attention. They include removing vegetation, grading and back-filling erosion ditches on the downstream face of the dam, and providing adequate drainage along the toe of the dam.

Two saturated areas were also noted near the siphon pipe (above the low level outlet pipe). The zones of saturation and hydrophilic vegetation extended from the dam toe to a point 13 feet below the dam crest.

b. Appurtenant Structures.

1. Spillway. The spillway was modified in 1969 when two feet of concrete was added to the weir crest in order to provide additional reservoir depth and surface area for recreational use. This spillway cap has since cracked and rotated somewhat (see Photograph 3). Since the cap only represents the upper two feet of the weir crest, the situation is not considered critical; however, it should be noted that the weir was also reshaped and the spillway sidewalls were not raised accordingly when the crest was raised, both of which have led to a reduction in the actual capacity of the spillway.

Moderate scaling, minor cracking and efflorescence were noted on the spillway apron and sidewalls, but the overall condition of the spillway is considered fair.

2. Outlet Works. The low level outlet works at Gallo Dam consists of an 18-inch diameter steel pipe encased in concrete. The dam owner reports that a concrete lid covers the small riser on the upstream end of the pipe as shown on Figure 4. A galvanized steel cable is attached to the lid and to the dam crest by an embedded metal anchor. A 16-inch diameter steel pipe siphon was added to the facility in 1973 to afford the ability to lower the reservoir to about 6 feet below normal pool, if necessary. The siphon was operated in the presence of the inspection team, but the low level outlet has apparently never been utilized. According to the owner, a diver replaced the steel cable lid attachment in 1978.

6.2 Design and Construction Techniques.

No information is available concerning the details of design. Historical documents contained within PennDER files



indicate that the site is underlain by minable coal, and that measures were taken to preclude deep mining beneath the dam and reservoir area. No formal specifications were prepared for construction; however, soil placement and compaction criteria were amended to the construction permit by State reviewers.

#### 6.3 Past Performance.

The owner reported that to his knowledge the facility has never overtopped, and that the maximum water level that he recalls was 14 to 16 inches above the spillway crest, or about 2 feet below the dam crest. A portion of the concrete spillway adjacent to the plunge pool was dislodged, apparently during a large storm, but remedial measures appear to be performing adequately

#### 6.4 Seismic Stability.

The dam is located in Seismic Zone 1, and is thus subject to minor earthquake induced dynamic forces. Due to the lack of data concerning the engineering characteristics of the materials used to construct the dam, the possible high phreatic surface above the low level outlet, and the apparent dumped (and uncompacted) condition of the soil near the downstream side of the crest, it cannot be presently assumed that the facility could tolerate even minor earthquake induced dynamic forces.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. Visual observations indicate that the facility is in fair condition. Hydrologic and hydraulic calculations performed during this investigation indicate that the facility will pass and/or store only 13 percent of the PMF prior to embankment overtopping. Based on screening criteria supplied by the Department of the Army, Office of Chief of Engineers, the spillway is deemed to be seriously inadequate, and the facility is considered unsafe, non-emergency.

Structural deficiencies noted by the inspection team during the field investigation included some erosion of the downstream slope, and a saturated downstream dam face in the vicinity of the low level outlet pipe and siphon. Additionally, dense vegetation and cut trees strewn on the downstream face preclude an accurate evaluation of its condition.

b. Adequacy of Information. The available information is considered sufficient to make an adequate Phase I assessment of the facility.

c. Urgency. Because of the seriously inadequate spillway, a warning system should be implemented immediately. Additional studies, as recommended below, should be carried out without delay.

d. Necessity for Additional Investigations. Additional investigations to more accurately determine the structural stability and hydraulic adequacy of the facility are considered necessary.

7.2 Recommendations/Remedial Measures.

Due to the seriously inadequate spillway classification, the facility is considered unsafe. Failure is not considered imminent; however, the owner should immediately develop a warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

In addition, it is recommended that the owner:

a. Have the facility studied by a registered professional engineer experienced in the hydraulics and hydrology

of dams, and implement the measures necessary to make the facility hydraulically adequate.

b. Cut the overgrowth and clear all brush from along the downstream embankment slope and toe to permit detailed inspection of the facility.

c. Have the facility inspected by a registered engineer experienced in the design and construction of earth dams to assess the stability of the embankment, particularly in the vicinity of observed saturation near the siphon, and take necessary remedial measures as recommended.

d. Provide positive controlled drainage of the flow observed along the abutment-embankment contact and immediately downstream of the toe area to eliminate the ponding and swamp-like conditions.

e. Regrade and seed the embankment crest and downstream slope to eliminate concentrated runoff and erosion ditches, and provide a smooth surface amenable to maintenance and inspection.

f. Provide a means whereby the low level outlet pipe can be closed, as well as opened, on its upstream side, at all times.

g. Develop formal manuals to ensure continued care, maintenance, and proper operation of the facility.

APPENDIX A

CHECK LIST - ENGINEERING DATA



CHECK LIST  
ENGINEERING DATA  
PHASE I

NAME OF DAM: Lake Gloria Dam  
NDI#: PA-233 PENNDER#: 56-91

PAGE 1 OF 5

ITEM	REMARKS	NDI# PA -
PERSONS INTERVIEWED AND TITLE	Mr. John E. Gallo - owner.	
REGIONAL VICINITY MAP	See Appendix G. (U.S.G.S. 7.5 minute topographic quadrangles: Boswell and Ligonier, PA).	
CONSTRUCTION HISTORY	Construction completed in 1958 by the Latrobe Construction Company. Original design by the Neilan Engineers. Data available in PennDER files.	
AVAILABLE DRAWINGS	PennDER files contain Drawings and sections; however, field inspection indicates they are not as-built.	
TYPICAL DAM SECTIONS	See Figure 3, Appendix F.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Figure 4, Appendix F. Siphon (16-inch diameter steel pipe) added around 1973.	

## ENGINEERING DATA (CONTINUED)

PAGE 2 5

ITEM	REMARKS	NDI# PA - 00233
SPILLWAY: PLAN SECTION DETAILS	Spillway weir modified in 1969 by reshaping and raising the crest by about two feet (a rectangular-shaped concrete cap was placed over the original trapezoidal-shaped weir). Spillway sidewalls raised only about 6 inches. See Figure 4 for original design.	
OPERATING EQUIPMENT PLANS AND DETAILS	Galvanized steel cable used to lift concrete cap from small riser on upstream side of low level outlet.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	None available.	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	None available.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	None available.	

## ENGINEERING DATA (CONTINUED)

PAGE 3 OF 5

ITEM	REMARKS	NDI# PA - 00233
BORROW SOURCES	Not known. Probably from within reservoir.	
POST CONSTRUCTION DAM SURVEYS	None.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	PennDER inspection reports of 1958 and 1963, available in PennDER files.	
HIGH POOL RECORDS	14 inches to 16 inches over spillway weir according to owner.	
MONITORING SYSTEMS	None.	
MODIFICATIONS	Siphon pipe added in 1973. Concrete added to sidewalls and concrete cap added to spillway weir in 1969. Material added to embankment crest in 1974.	



## ENGINEERING DATA (CONTINUED)

PAGE 4 5

ITEM	REMARKS	NDI#	PA	00233
PRIOR ACCIDENTS OR FAILURES	Toe of spillway washed away during large storm. Remedial concrete placed to prevent further erosion.			
MAINTENANCE: RECORDS MANUAL	No records or formal manual are available. Maintenance such as clearing slope, replacing riprap, patching spillway, etc., done on unscheduled basis by the owner.			
OPERATION: RECORDS MANUAL	No records or formal manual are available.			
OPERATIONAL PROCEDURES	Siphon left open at all times. Otherwise, self-regulating.			
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	None.			
MISCELLANEOUS	Owner resides in Ligonier, approximately 15 minutes from the dam. Facility opened to the public from Memorial Day through Labor Day.			



CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

NDI ID # PA-00233

PENN DER ID # 56-91

PAGE 5 OF 5

SIZE OF DRAINAGE AREA: 3.8 square miles

ELEVATION TOP NORMAL POOL: 1847.3 STORAGE CAPACITY: 330 acre-feet

ELEVATION TOP FLOOD CONTROL POOL: -- STORAGE CAPACITY: --

ELEVATION MAXIMUM DESIGN POOL: -- STORAGE CAPACITY: --

ELEVATION TOP DAM: 1850.5 STORAGE CAPACITY: 440 acre-feet

SPILLWAY DATA

CREST ELEVATION: 1847.3 feet

TYPE: Concrete chute channel, with discharges controlled by a concrete weir structure.

CREST LENGTH: 39 feet

CHANNEL LENGTH: 60 feet

SPILOVER LOCATION: right abutment

NUMBER AND TYPE OF GATES: none

OUTLET WORKS

TYPE: 18-inch diameter steel low level blowoff pipe encased in concrete; 16-inch diameter steel siphon pipe.

LOCATION: both located near left side of spillway.

ENTRANCE INVERTS: 1833 feet (blowoff; design)

EXIT INVERTS: 1822 feet (blowoff; field measurement)

EMERGENCY DRAWDOWN FACILITIES: Galvanized steel cable connected to embankment crest and to concrete lid covering blowoff inlet.

HYDROMETEOROLOGICAL GAGES

TYPE: None

LOCATION: N/A

RECORDS: N/A

MAXIMUM NON-DAMAGING DISCHARGE: 14 inches to 16 inches over spillway weir crest (according to owner).

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
BY DJS DATE 9-8-79 PROJ. NO. 78-617-233  
CHKD. BY WJV DATE 9-9-79 SHEET NO. 1 OF 21

**gai**  
CONSULTANTS  
Engineers • Geologists • Planners  
Environmental Specialists

### DAM STATISTICS

HEIGHT OF DAM  $\approx$  29 FT (FIELD MEASURED)

(MEASURED FROM LOW TOP OF DAM EL. 1853.5 FT  
TO INVERT OF BLOWOFF EL. 1822.0 FT)

MAXIMUM POOL STORAGE CAPACITY  $\approx$  440 AC-FT (HEC-1)  
AT LOW TOP OF DAM

NORMAL POOL STORAGE CAPACITY  $\approx$  330 AC-FT (HEC-1)

DRAINAGE AREA  $\approx$  3.8 SQUARE MILES  
[ PLANIMETERED OFF  
USGS 7.5 MINUTE QUADS:  
LIGONIER AND DOWELL, PA ]

### DAM CLASSIFICATION

DAM SIZE - SMALL (REF 1, TABLE 1)

HAZARD CLASSIFICATION - HIGH (FIELD OBSERVATION)

REQUIRED SDF -  $\frac{1}{2}$  PMF TO PMF (REF 1, TABLE 3)

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
BY DJS DATE 9-8-79 PROJ. NO. 78-617-233  
CHKD. BY WJV DATE 9-8-79 SHEET NO. 2 OF 21

**gai**  
CONSULTANTS  
Engineers • Geologists • Planners  
Environmental Specialists

### HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE  $\approx$  4.0 MILES

$L_{CA} = 2.0$  MILES (MEASURED ALONG THE LONGEST WATERCOURSE  
FROM THE DAM CREST TO BASIN CENTROID)

NOTE 1: VALUES OF  $L$  AND  $L_{CA}$  WERE MEASURED FROM THE  
USGS 7.5 MINUTE QUADS OF LIGONIER AND DAWELL, PA.  
ALL HYDROGRAPH VARIABLES ARE DEFINED IN REFERENCE 2,  
IN THE SECTION ENTITLED "SNYDER SYNTHETIC UNIT  
HYDROGRAPH".

$$C_t = 1.6$$

$$C_p = 0.45$$

[ SUPPLIED BY COE, ZONE 24,  
OHIO RIVER BASIN ]

$$t_p = \text{SNYDER'S STANDARD LAG} = 1.6 (L \times L_{CA})^{0.3}$$

$$t_p = 1.6 (4.0 \times 2.0)^{0.3} \approx 2.99 \text{ HOURS}$$

### RESERVOIR ELEVATION - STORAGE RELATIONSHIP

THE RESERVOIR ELEVATION-STORAGE RELATIONSHIP IS COMPUTED  
INTERNALLY BY THE HEC-1 PROGRAM, BASED ON THE FOLLOWING  
ELEVATION - SURFACE AREA - STORAGE INFORMATION:

DESIGN NORMAL POOL STORAGE  $\approx$  260 ACRE-FT  
DESIGN NORMAL POOL ELEVATION  $\approx$  1845.0 FT  
DESIGN NORMAL POOL SURFACE AREA (SA)  $\approx$  30.3 ACRES

[ SEE  
NOTE  
2 ]



SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
 BY DJS DATE 9-8-79 PROJ. NO. 78-617-233  
 CHKD. BY WJV DATE 9-8-79 SHEET NO. 3 OF 21



NOTE 2: DESIGN NORMAL POOL SURFACE AREA AND STORAGE VALUES OBTAINED FROM "REPORT UPON THE APPLICATION OF COND GALLO (FOR THE CONSTRUCTION OF A DAM ACROSS BEAVERDAM RUN, IN JENNER TOWNSHIP, SOMERSET COUNTY", AS FOUND IN PENN DER FILES. THE ACTUAL REPORTED STORAGE VALUE WAS 85.9 MILLION GALLONS. DESIGN NORMAL POOL ELEVATION OBTAINED FROM APPENDIX F, FIG 4.

SA @ EL. 1860 = 47 ACRES  
 SA @ EL. 1880 = 86 ACRES

PLANIMETERED OFF USGS  
 7.5 MINUTE QUADS: LIGONIER,  
 BOWELL, PA

NORMAL POOL ELEVATION = 1847.3 FT (FIELD MEASURED)  
 LOW TOP OF DAM ELEVATION = 1850.5 FT

RATE OF SA INCREASE PER FOOT OF RESERVOIR ELEVATION RISE:

$$\Delta SA / \Delta H = \frac{(47-30)}{(1860-1845)} = 1.1 \text{ AC/FT}$$

$$\therefore SA @ 1847.3 = 30 + (1.1)(1847.3-1845) = 33 \text{ ACRES}$$

$$SA @ 1850.5 = 30 + (1.1)(1850.5-1845) = 36 \text{ ACRES}$$

RESERVOIR ELEVATION AT "0" STORAGE:

STORAGE @ DESIGN NORMAL POOL ELEV =  $\frac{1}{3}HA = 360 \text{ AC-FT}$

(CONIC  
 METHOD)

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
 BY DJS DATE 9-8-79 PROJ. NO. 78-617-233  
 CHKD. BY WJV DATE 9-3-79 SHEET NO. 4 OF 21



SA @ DESIGN NORMAL POOL = 30 ACRES

$$\therefore H \approx \frac{(3)(260)}{(30)} = 26 \text{ FT}$$

ZERO VOLUME ELEVATION =  $1845 - 26 = 1819 \text{ FT}$

NOTE 3: IN ORDER TO COMPUTE AN ELEVATION-STORAGE RELATIONSHIP, WITH A STORAGE OF 260 ACRE-FT AT ELEVATION 1845, THE ABOVE COMPUTED "0"-STORAGE ELEVATION MUST BE INPUT INTO THE HEC-1 PROGRAM. THE ACTUAL DESIGN MINIMUM RESERVOIR ELEVATION IS ON THE ORDER OF 1829 FT (FIG 4); HOWEVER, IT IS FELT THAT THIS ELEVATION COULD BE IN ERROR.

### PMP CALCULATIONS

- APPROXIMATE RAINFALL INDEX = 24 INCHES, CORRESPONDING TO A DURATION OF 24 HRS AND AN AREA OF 300 SQ. MILES, LOCATED IN SOUTH CENTRAL PENNSYLVANIA. (REF 3, FIG 1)
- DEPTH-AREA-DURATION ZONE # 7 (REF 3, FIG 1)
- DRAINAGE AREA = 3.8 SQ. MI.; ASSUME DATA CORRESPONDING TO A 10-SQ. MI. AREA IS REPRESENTATIVE OF THIS BASIN:

<u>DURATION (HRS)</u>	<u>PERCENT OF INDEX RAINFALL</u>
6	102
12	130
24	130
48	140

(REF 3, FIG 2)

- HOB BROOK ADJUSTMENT FACTOR FOR A = 4 SQ MI: 0.80


(HEC-1)

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
 BY WJV DATE 9-8-79 PROJ. NO. 78-617-233  
 CHKD. BY DLB DATE 9-8-79 SHEET NO. 5 OF 21


**gai**  
 CONSULTANTS, INC  
 Engineers • Geologists • Planners  
 Environmental Specialists

## SPILLWAY CAPACITY

- PROFILE OF SPILLWAY : (NOT TO SCALE)  
 (OBTAINED FROM FIELD MEASUREMENTS AND OBSERVATIONS, AND APPENDIX F)



- CROSS-SECTION OF SPILLWAY : (NOT TO SCALE)  
 (OBTAINED FROM FIELD MEASUREMENTS AND OBSERVATIONS, AND APPENDIX F)





SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
BY WJV DATE 9-9-79 PROJ. NO. 79-617-233  
CHKD. BY DJS DATE 9-8-79 SHEET NO. 6 OF 21



- THE SPILLWAY IS A CONCRETE CHUTE CHANNEL, WITH DISCHARGES CONTROLLED BY A CONCRETE WEIR STRUCTURE. THE PRESENT WEIR IS RECTANGULAR IN CROSS-SECTION, AND IS THE RESULT OF CAPPING A TRAPEZOIDAL-SHAPED WEIR SECTION. FLOW OVER THE WEIR CAN BE DEFINED BY :

$$Q = CLH^{3/2} \quad (\text{REF 5, PG 5-3})$$

WHERE  $Q$  = DISCHARGE OVER WEIR, IN CFS;  
 $L$  = LENGTH OF WEIR CREST  $\approx$  39 FT (FIELD MEASURED);  
 $H$  = HEIGHT OF RESERVOIR ABOVE SPILLWAY CREST  
EL 1847.3 FT, ASSUMED DESIGN HEAD ( $H_0$ )  
 $\approx$  3.2 FT;  
 $C$  = DISCHARGE COEFFICIENT  $\approx$  3.33 @ ASSUMED DESIGN HEAD

NOTE 4 : THE WEIR HAS A FLAT CREST WHOSE BREADTH IS ABOUT 1 FT, AND THE US AND DS SIDESLOPES ARE VERTICAL. THEREFORE, ALTHOUGH THE WEIR IS NOT ACTUALLY SHARP-CRESTED, IT IS ASSUMED THAT THE REPRESENTATIVE WEIR COEFFICIENT AT THE DESIGN HEAD IS ON THE ORDER OF 3.33 (CORRESPONDING TO A SHARP-CRESTED WEIR; REF 5, PG 5-7).

- APPROACH CHANNEL LOSSES @ DESIGN FLOW :

a) APPROXIMATE APPROACH CHANNEL LENGTH = 100 FT } INFERRED FROM  
AVERAGE APPROACH CHANNEL WIDTH  $\approx$  50 FT } APPENDIX F  
FIG 2

LEFT SIDE OF APPROACH CHANNEL CONSISTS OF THE LEFT SPILLWAY WINGWALL WHICH VARIES FROM ABOUT 7.6 FT ABOVE THE CHANNEL AT THE WEIR TO ABOUT 6.6 FT ABOVE THE

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJVDATE 9-8-79PROJ. NO. 79-617-233CHKD. BY DJSDATE 9-8-79SHEET NO. 7 OF 21

Engineers • Geologists • Planners  
Environmental Specialists

CHANNEL AT THE CHANNEL ENTRANCE. THE WINGWALL IS VERTICAL. (INFORMATION FROM FIG 4, AND FIELD MEASUREMENTS)

RIGHT SIDE OF APPROACH CHANNEL CONSISTS OF THE VEGETATED RIGHT ABUTMENT WHICH HAS AN ESTIMATED 2H TO 1V SIDESLOPE FOR ALL APPROACH CHANNEL DEPTHS. (INFORMATION FROM FIELD OBSERVATION)

∴ @ RESERVOIR EL 1350.5 FT (LOW TOP OF DAM) THE MAXIMUM APPROACH CHANNEL DEPTH = FOREBAY DEPTH + HEAD OVER WEIR  $\approx 3.9 \text{ FT} + 3.2 \text{ FT} \approx 7.1 \text{ FT}$

⇒ AVERAGE APPROACH CHANNEL FLOW AREA =  $A_a$

$$A_a \approx (50 \text{ FT} \times 7.1 \text{ FT}) + \left[ \frac{1}{2} (2 \times 7.1 \text{ FT}) (7.1 \text{ FT}) \right] \\ \approx 405 \text{ FT}^2$$

b) INITIAL ESTIMATE OF DISCHARGE @ EL 1350.5 FT :

$$Q \approx (3.33)(39 \text{ FT})(3.2 \text{ FT})^{3/2} \approx 740 \text{ CFS}$$

c) AVERAGE APPROACH CHANNEL VELOCITY  $\approx Q/A_a$

$$V_a \approx 740 \text{ CFS} / 405 \text{ FT}^2 \approx 1.8 \text{ FPS}$$

⇒ AVERAGE APPROACH VELOCITY HEAD =  $h_a \approx V_a^2 / 2g$

$$h_a \approx (1.8 \text{ FPS})^2 / 2g \approx 0.05 \text{ FT}$$

ASSUMING THAT THE APPROACH CHANNEL ENTRANCE LOSS  $\approx 0.1 h_a$  (REF 4, PG 379) ⇒ 0.01 FT

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY

WJV

DATE

9-8-79

PROJ. NO.

78-617-233

CHKD. BY

DSS

DATE

9-8-79

SHEET NO.

8

OF

21



Engineers • Geologists • Planners  
Environmental Specialists

$$d) \text{ APPROACH CHANNEL FRICTION LOSS} = h_f \approx \left[ \frac{v_a^n}{1.49 R_h^{2/3}} \right]^2 \times L_c$$

WHERE  $L_c$  = LENGTH OF APPROACH CHANNEL  $\approx 100$  FT  
(SEE SHEET 6);

$n$  = MANNING'S ROUGHNESS COEFFICIENT  $\approx 0.05$   
(REF 7, PG 112; EXCAVATED CHANNEL, COBBLE  
BOTTOM, AND VEGETATED RIGHT SIDE);

$R_h$  = HYDRAULIC RADIUS = FLOW AREA / WETTED PERIMETER  
FLOW AREA =  $A_c \approx 405$  FT<sup>2</sup>, PARTIAL WETTED  
PERIMETER FOR RIGHT SIDEWALL  $\approx 15.9$  FT,  
PARTIAL WETTED PERIMETER FOR LEFT  
SIDEWALL  $\approx 7.0$  FT, TOTAL WETTED PERIMETER  
 $\approx 50$  FT +  $15.9$  FT +  $7.0$  FT  $\approx 72.9$  FT  
 $\Rightarrow R_h \approx 405 \text{ FT}^2 / 72.9 \text{ FT} \approx 5.6$  FT

$$\therefore h_f \approx (100 \text{ FT}) \times \left[ \frac{(1.9 \text{ FPS})(0.05)}{1.49 (5.6 \text{ FT})^{2/3}} \right]^2 \approx 0.04$$

$$\therefore \text{TOTAL APPROACH CHANNEL LOSS} \approx 0.01 + 0.04 \approx 0.05 \text{ FT}$$

$$\Rightarrow \text{ACTUAL EFFECTIVE HEAD} \approx 3.2 \text{ FT} - 0.05 \text{ FT} \approx 3.15 \text{ FT}$$

$$\Rightarrow \text{SPILLWAY CAPACITY} \approx (3.33)(39 \text{ FT})(3.15 \text{ FT})^{3/2} \\ \approx 730 \text{ CFS}$$

(SUBMERGENCE EFFECTS ARE NEGLIGIBLE)



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-8-79

PROJ. NO.

78-617-233

CHKD. BY

DJS

DATE

9-8-79

SHEET NO.

9

OF

21



### SPILLWAY RATING CURVE

AS THE HEAD ABOVE THE WEIR BECOMES SMALL, THE ROUGHNESS OF THE CREST AND THE CONTACT PRESSURE BETWEEN THE WATER AND THE CREST EXERT A LARGER INFLUENCE ON DISCHARGES. THAT IS, THE C-VALUES DECREASE WITH DECREASING HEAD. THE OPPOSITE TREND OCCURS FOR HIGHER HEADS. THEREFORE, ASSUME THAT THE DISCHARGE COEFFICIENT - HEAD RELATIONSHIP FOR THE ACTUAL WEIR STRUCTURE CAN BE REPRESENTED BY THAT FOR AN OGEE-SHAPED WEIR (REF 4, PG 378, FIG 250). THE MAXIMUM HEAD PRIOR TO OVERTOPPING OF THE EMBANKMENT IS ABOUT 3.2 FT, WHICH WILL BE ASSUMED TO BE THE DESIGN HEAD ( $H_0$ ). THE DESIGN DISCHARGE COEFFICIENT ( $C_0$ ) WILL BE ASSUMED TO EQUAL 3.33 (SHEET 6).

ALL DISCHARGES OVER THE WEIR ARE DEFINED BY THE  $Q = CLH^{3/2}$  RELATIONSHIP AS GIVEN ON SHEET 6. THE HEAD OVER THE WEIR WILL BE ADJUSTED TO ACCOUNT FOR APPROACH CHANNEL LOSSES BY PROPORTIONING THE COMPUTED LOSS OF 0.05 FT AT EL 1850.5 FT.

SPILLWAY RATING CURVE IS GIVEN ON SHEET 10.

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-9-79

PROJ. NO.

79-617-233

CHKD. BY DJS

DATE

9-8-79

SHEET NO.

10 OF 21

Engineers • Geologists • Planners  
Environmental Specialists

RESERVOIR ELEVATION (FT)	① H (FT)	② $H/H_0$ (FT/FT)	③ $C/C_0$	④ C	⑤ ESTIMATED APPROACH LOSS (FT)	⑥ EFFECTIVE HEAD: $H_e$ (FT)	⑦ Q (CFS)
1847.3	0	-	-	-	-	0	0
1848.0	0.7	0.22	0.96	2.86	0.01	0.69	60
1849.0	1.7	0.53	0.93	3.10	0.03	1.67	260
1850.0	2.7	0.84	0.98	3.26	0.04	2.66	550
1850.5	3.2	1.0	1.0	3.33	0.05	3.15	730
1851.0	3.7	1.16	1.02	3.40	0.06	3.64	920
1852.0	4.7	1.47	1.06	3.53	0.07	4.63	1370
1853.0	5.7	1.78	1.07	3.56	0.09	5.61	1840
1854.0	6.7	2.09	1.08	3.60	0.10	6.60	2380
1855.0	7.7	2.41	1.09	3.63	0.12	7.58	2950
1856.0	8.7	2.72	1.10	3.66	0.14	8.56	3570

①  $H = \text{RESERVOIR ELEVATION} - 1847.3 \text{ FT}$  ;② REF 4, PG 378, FIG 250, BASED ON  $H/H_0$  ;③  $C = C_0 \times 3.33$  ;④ ESTIMATED APPROACH LOSS  $\approx (H/H_0) \times 0.05 \text{ FT}$  ;⑤  $H_e \approx H - (\text{ESTIMATED APPROACH LOSS})$  ;⑥  $Q = C (39 \text{ FT}) H_e^{3/2}$

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
 BY WJV DATE 9-9-79 PROJ. NO. 79-617-233  
 CHKD. BY DJS DATE 9-8-79 SHEET NO. 11 OF 21



## EMBANKMENT RATING CURVE

- LENGTH OF EMBANKMENT SUBMERGED VS RESERVOIR ELEVATION (BASED ON FIELD MEASUREMENTS)

RESERVOIR ELEVATION (FT)	EMBANKMENT LENGTH (FT)
1850.5	0
1850.6	150
1850.7	430
1850.9	540
1851.0	570
1851.2	600
1852.6	660
1853.0	670
1854.0	680
1855.0	700
1856.0	720

BASED PARTIALLY ON THE  
 ABUTMENT SIDE SLOPES:  
 LEFT ABUTMENT  $\Rightarrow$  12H TO 1V  
 RIGHT ABUTMENT  $\Rightarrow$  5H TO 1V

- ASSUME THE EMBANKMENT ACTS LIKE A BROAD-CRESTED WEIR WHEN OVERTOPPED, W/ DISCHARGE DEFINED BY:

$$Q = CL\bar{H}^{3/2} \quad (\text{SHEET 6})$$

WHERE  $L$  = LENGTH OF EMBANKMENT INUNDATED, IN FT;  
 $C$  = DISCHARGE COEFFICIENT FOR EMBANKMENTS  
 $= f(L^{1/2})$  WHERE  $L$  = BREADTH OF CREST  $\approx$  30 FT,  
 AND REF 12, PG 46); AND  
 $\bar{H}$  = AVERAGE "FLOW-AREA WEIGHTED" HEAD ABOVE  
 THE LOW TOP OF DAM EL 1850.5 FT. ASSUME  
 THE LOW POINT OCCURS AT THE MIDDLE OF THE



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-9-79

PROJ. NO.

78-617-233CHKD. BY DJS

DATE

9-8-79

SHEET NO.

12 OF 21Engineers • Geologists • Planners  
Environmental Specialists

EMBANKMENT, AND THAT THE INUNDATED EMBANKMENT LENGTH IS EVENLY DISTRIBUTED ON EITHER SIDE OF THE LOW POINT. SINCE THE EMBANKMENT PROFILE IS ROUGHLY TRIANGULAR IN SHAPE  $\Rightarrow$  AVERAGE HEAD  $\approx 1/2$  MAXIMUM HEAD.

RESERVOIR ELEVATION (FT)	① MAXIMUM HEAD H (FT)	② AVERAGE HEAD $\bar{H}$ (FT)	$\bar{H}/2$ (FT/FT)	③ C	④ L (FT)	⑤ Q (CCFS)
1850.5	0	0	-	-	0	0
1850.6	0.1	0.05	0.0	2.90	150	0
1850.7	0.2	0.10	0.0	2.92	430	40
1850.9	0.4	0.20	0.01	2.97	540	140
1851.0	0.5	0.25	0.01	2.99	570	210
1851.2	0.7	0.35	0.01	3.01	600	370
1852.6	2.1	1.05	0.04	3.04	660	2160
1853.0	2.5	1.25	0.04	3.04	670	2850
1854.0	3.5	1.75	0.06	3.04	690	4790
1855.0	4.5	2.25	0.09	3.05	700	7210
1856.0	5.5	2.75	0.09	3.05	720	10010

① MAXIMUM HEAD =  $H$  = RESERVOIR ELEVATION - 1850.5 FT;

② AVERAGE HEAD =  $\bar{H}$  =  $H/2$ ;

③ REF 12, PG 46, BASED ON  $\bar{H}/2$ ;

④ FROM SHEET 11;

⑤  $Q = CL \bar{H}^{3/2}$

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE 9-9-79

PROJ. NO. 79-617-233

CHKD. BY DJS

DATE 9-8-79

SHEET NO. 13 OF 21

Engineers • Geologists • Planners  
Environmental SpecialistsTOTAL FACILITY RATING CURVE

TOTAL DISCHARGE = SPILLWAY Q + EMBANKMENT Q

RESERVOIR ELEVATION (FT)	①	②	TOTAL Q (CFS)
	SPILLWAY Q (CFS)	EMBANKMENT Q (CFS)	
1847.3	0	-	0
1848.0	60	-	60
1849.0	260	-	260
1850.0	550	-	550
LOW TOP OF DAM	1850.5	730	730
	1850.6 *	770	770
	1850.7 *	810	850
	1850.9 *	880	1020
	1851.0	920	1130
	1851.2 *	1010	1380
	1852.0	1370	2760
	1852.6 *	1650	3910
	1853.0	1840	4690
	1854.0	2380	7170
	1855.0	2950	10160
	1856.0	3570	13530

① FROM SHEET 10

② FROM SHEET 12

\* STRAIGHT-LINE INTERPOLATION

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

NDI ID # PA-00233  
PENN DER ID # 56-91  
PAGE 5 OF 5

SIZE OF DRAINAGE AREA: 3.8 square miles  
ELEVATION TOP NORMAL POOL: 1847.3 STORAGE CAPACITY: 330 acre-feet  
ELEVATION TOP FLOOD CONTROL POOL: -- STORAGE CAPACITY: --  
ELEVATION MAXIMUM DESIGN POOL: -- STORAGE CAPACITY: --  
ELEVATION TOP DAM: 1850.5 STORAGE CAPACITY: 440 acre-feet

SPILLWAY DATA

CREST ELEVATION: 1847.3 feet  
TYPE: Concrete chute channel, with discharges controlled by a concrete weir structure.  
CREST LENGTH: 39 feet  
CHANNEL LENGTH: 60 feet  
SPILLOVER LOCATION: right abutment  
NUMBER AND TYPE OF GATES: none

OUTLET WORKS

TYPE: 18-inch diameter steel low level blowoff pipe encased in concrete; 16-inch diameter steel siphon pipe.  
LOCATION: both located near left side of spillway.  
ENTRANCE INVERTS: 1833 feet (blowoff; design)  
EXIT INVERTS: 1822 feet (blowoff; field measurement)  
EMERGENCY DRAWDOWN FACILITIES: Galvanized steel cable connected to embankment crest and to concrete lid covering blowoff inlet.

HYDROMETEOROLOGICAL GAGES

TYPE: None  
LOCATION: N/A  
RECORDS: N/A

MAXIMUM NON-DAMAGING DISCHARGE: 14 inches to 16 inches over spillway weir crest (according to owner).



5/15/68

CHANNEL SLIDE A 6, 2011

INFORMATION DERIVED  
FROM FIELD MEASUREMENT  
AND CORRELATION, AND  
USSR TOPS MAP


Y  
V  
L  
A  
C  
S  
Z

3. ASSUME A NATURAL SECTION OF 10-11M DEATH ~ 35MT WITH  
CAVITY IDEALLY REPRESENT THE SPIDRE

# STAT 200 (F)

# DOWNSTREAM ROUTING SECTIONS

SHEET 15 OF 21










# DOWNSTREAM ROUTING SECTIONS

SHEET 17 OF 21



SUBJECT DAM SAFETY INSPECTION  
GALLO DAM

BY WJV DATE 9-10-79 PROJ. NO. 79-G17-233


CHKD. BY DLB DATE 9-12-79 SHEET NO. 18 OF 21



Engineers • Geologists • Planners  
Environmental Specialists

## BREACH ASSUMPTIONS

- TYPICAL BREACH SECTION :



- HEC-1-DAM BREACHING ANALYSIS INPUTS :

(BREACHING WILL COMMENCE WHEN THE RESERVOIR LEVEL REACHES THE TOP OF DAM ELEVATION).

PLAN NUMBER AND COMMENT	BREACH BOTTOM WIDTH (FT)	MAX BREACH DEPTH (FT)	SECTION SIDESLOPES	* BREACH TIME (HR)	WSEL @ STATE OF FAILURE (FT)
① MIN BREACH SECT, MIN FAIL TIME	0	29	1/2 H to 1 V	0.5	1950.5
② MAX BREACH SECT, MIN FAIL TIME	350	29	3/4 to 1 V	0.5	1950.5
③ MIN BREACH SECT, MAX FAIL TIME	0	29	1/2 H to 1 V	4.0	1950.5
④ MAX BREACH SECT, MAX FAIL TIME	350	29	3/4 to 1 V	4.0	1950.5
⑤ AVERAGE POSSIBLE CONDITIONS	100	29	1 H to 1 V	2.0	1950.5

SUBJECT DAM SAFETY INSPECTION  
GALLO DAM  
 BY WJV DATE 9-10-79 PROJ. NO. 78-617-233  
 CHKD. BY DLB DATE 9-12-79 SHEET NO. 19 OF 21

**gai**  
 CONSULTANTS, INC  
 Engineers • Geologists • Planners  
 Environmental Specialists

- THE BREACH ASSUMPTIONS LISTED ON SHEET 18 ARE BASED SOMEWHAT ON INFORMATION CONCERNING EARTH DAM BREACHING PROVIDED BY THE COE, BALTIMORE DISTRICT; AND ALSO ON THE PHYSICAL CONSTRAINTS OF THE DAM AND SURROUNDING TERRAIN:

CONSTRAINT	VALUE
HEIGHT OF DAM	≈ 29 FT (FIELD MEASURED)
EMBANKMENT CREST LENGTH:	
TO RIGHT OF SPWY	≈ 50 FT
TO LEFT OF SPWY	≈ 610 FT
TOTAL	≈ 660 FT
	} FIELD MEASURED
VALLEY BOTTOM WIDTH	≈ 350 FT (FIG 3)
VALLEY SIDESLOPES ADJACENT TO DAM:	
RIGHT WALL	3H TO 1V
LEFT WALL	7H TO 1V
	} FIG 3



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE 9-10-79

PROJ. NO. 73-617-233

CHKD. BY DLB

DATE 9-12-79

SHEET NO. 20 OF 21

Engineers • Geologists • Planners  
Environmental Specialists

## HEC-1-DAM BREACHING ANALYSIS OUTPUT :

RESERVOIR DATA

## UNDER 0.15 PMF BASE FLOW CONDITIONS -

* PLAN NUMBER	VARIABLE BREACH BOTTOM WIDTH (FT)	ACTUAL MAX FLOW DURING FAIL TIME (CFS)	CORRESPONDING TIME OF FLOW (HR)	INTERPOLATED OR HEC-1 ROUTED MAX FLOW DURING FAIL TIME (CFS)	CORRESPONDING TIME OF FLOW (HR)	ACTUAL PEAK FLOW THROUGH DAM (CFS)	CORRESPONDING TIME OF FLOW (HR)	TIME OF INITIAL BREACH (HR)
①	0	5168	43.17	5168	43.17	5168	43.17	42.67
②	350	20085	42.90	17695	42.83	20085	42.90	42.67
③	0	2538	46.67	2538	46.67	2538	46.67	42.67
④	350	3662	43.50	3662	43.50	3662	43.50	42.67
⑤	100	5723	43.58	5647	43.67	5723	43.58	42.67

\* SEE TABLE ON SHEET 18

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

21

OF

21

Engineers • Geologists • Planners  
Environmental Specialists

## HEC-1-DAM BREACHING ANALYSIS OUTPUT :

DOWNSTREAM ROUTING DATA

## UNDER 0.15 PMF BASE FLOW CONDITIONS :

1. PLAN NUMBER	VARIABLE BREACH BOTTOM WIDTH (FT)	OUTPUT @ SECTION 6 LOCATED 15000 FT DS FROM DAM				OUTPUT @ SECTION 8 LOCATED 21050 FT DS FROM DAM			
		PEAK FLOW (CFS)	CORRESPONDING WSEL 2. (FT)	WSEL 3. W/O BREACH (FT)	4. ΔELEV (FT)	PEAK FLOW (CFS)	CORRESPONDING WSEL 2. (FT)	WSEL 3. W/O BREACH (FT)	4. ΔELEV (FT)
①	0	2279	1814.8	1811.5	+3.3	2250	1806.3	1802.1	+4.2
②	350	3076	1815.9	1811.5	+4.4	2985	1807.9	1802.1	+5.9
③	0	1901	1814.3	1811.5	+2.8	1863	1805.3	1802.1	+3.2
④	350	2448	1815.0	1811.5	+3.5	2423	1806.7	1802.1	+4.6
⑤	100	2943	1815.7	1811.5	+4.2	2870	1807.7	1802.1	+5.6

1. SEETABLE ON SHEET 18 ;
2. WATER SURFACE ELEVATIONS CORRESPONDING TO BREACH OUTFLOWS (SUMMARY INPUT/OUTPUT SHEETS, SHEET P) ;
3. BASE FLOW ELEVATIONS CORRESPONDING TO THE PEAK 0.15 PMF AS INTERPOLATED FROM SHEET K, SUMMARY INPUT/OUTPUT SHEETS ;
4. ΔELEV = (CORRESPONDING WSEL) - (WSEL W/O BREACH)

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

A OF P

Engineers • Geologists • Planners  
Environmental Specialists

## OVERTOPPING

## SUMMARY INPUT/OUTPUT SHEETS

DAM SAFETY INSPECTION  
GALLO DAM \*\*\*\*\* OVERTOPPING ANALYSIS \*\*\*\*\*  
10-MINUTE TIME STEP AND 48-HOUR STORM DURATION

JOB SPECIFICATION

NO	MHR	MNIN	IDAY	IHR	IMIN	METC	IPLT	IPMT	INSTAN
200	0	10	0	0	0	0	0	0	0
			JUPER	NWT	LKURT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIUS= .10 .20 .30 .40 .50 1.00  
NPLAN= 1 NRTIU= 6 LRTIU= 1

\*\*\*\*\*

## SUB-AREA RUNOFF COMPUTATION

INFLOW INTO GALLO DAM RESERVOIR

ISTAO	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

## HYDROGRAPH DATA

LYDGC	LYNG	LYREA	SNAP	TRSDA	TRSPC	RATIO	JSNOM	ISAME	LOCAL
1	1	3.00	0.00	3.00	0.00	0.000	0	1	0

## PRECIP DATA

SPFE	PMS	R6	R12	R24	M48	R72	R96
0.00	24.00	102.00	120.00	130.00	140.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .000

INITIAL AND CONSTANT RATIO LOSS

S RATES AS PER COE

STRTL	CNSTL	ALSMX	RTIMP
1.00	.05	0.00	0.00

## LOSS DATA

INRPT	STRKR	DLTR	RTIOL	ERAIN	STRNS	RTIUK
0	0.00	0.00	1.00	0.00	0.00	1.00

## UNIT HYDROGRAPH DATA

TV= 2.99 CP= .45 NTA= 0

BASEFLOW PARAMETERS

AS PER COE

STRTU=	ORCSNE	RTIUK=
-1.50	-.05	2.00

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNIDER CP AND TP ARE: TC=18.54 AND H=24.31 INTERVALS



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

B OF P

Engineers • Geologists • Planners  
Environmental Specialists

UNIT	HYDROGRAPHIC	END-OF-PERIOD	UNDINATES	LAGE	2.39	HOURS	CP	.45	VOL	.96
5.	17.	36.	58.	83.	110.	140.	171.	203.	236.	
	292.	320.	341.	358.	371.	379.	383.	378.	307.	
	342.	330.	318.	307.	296.	286.	276.	267.	257.	
	240.	232.	223.	216.	208.	201.	194.	187.	181.	
	168.	163.	157.	152.	146.	141.	136.	132.	127.	
	118.	114.	110.	106.	103.	99.	96.	92.	89.	
	83.	80.	77.	75.	72.	70.	67.	65.	63.	
	58.	56.	54.	52.	51.	49.	47.	46.	44.	
	42.	40.	38.	37.	36.	34.	33.	32.	31.	
	29.	28.	27.	26.	25.	24.	23.	22.	22.	

MO. DA	HR. MM	PERIOD	RAIN	EXCS	LUSS	CUM. U
SUM	26.88	24.46	2.42	283874.		
	( 683. )	( 621. )	( 61. )	( 8038.42 )		

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5017.	1910.	981.	282588.
CMS	142.	54.	28.	8002.
INCHES	12.28	18.70	19.22	19.22
MM	311.98	474.94	488.08	488.08
AC-FT	2488.	3788.	3892.	3892.
THOUS CU M	3069.	4672.	4801.	4801.

PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	502.	191.	98.	282588.
CMS	14.	5.	3.	800.
INCHES	1.23	1.87	1.92	1.92
MM	31.20	47.49	48.81	48.81
AC-FT	249.	379.	389.	389.
THOUS CU M	307.	467.	480.	480.

0.1 PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	1003.	382.	196.	56518.
CMS	28.	11.	6.	1600.
INCHES	2.46	3.74	3.84	3.84
MM	62.40	94.99	97.62	97.62
AC-FT	498.	758.	778.	778.
THOUS CU M	614.	934.	960.	960.

0.2 PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	2509.	955.	491.	141294.
CMS	71.	27.	14.	4001.
INCHES	6.14	9.35	9.61	9.61
MM	155.99	237.47	244.04	244.04
AC-FT	1244.	1894.	1946.	1946.
THOUS CU M	1534.	2336.	2401.	2401.

0.5 PMF

RESERVOIR

INFLOW

HYDROGRAPHS

SUBJECT

DAM SAFETY INSPECTION  
GALLO DAMBY WJV

DATE

9-10-79

PROJ. NO.

78-617-233CHKD. BY DLB

DATE

9-12-79

SHEET NO.

C OF PEngineers • Geologists • Planners  
Environmental Specialists

## HYDROGRAPH ROUTING

## ROUTE INFLOW THROUGH RESERVOIR

ISTAQ	ICOMP	IECUN	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
101	1	0	0	0	0	1	0	0
ROUTING DATA								
QLOSS	CLLOSS	AVG	IRRES	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS	NSTUL	LAG	ANSKK	X	TSK	STUNA	ISPRAT	
1	0	0	0.000	0.000	0.000	-1847.	-1	
STAGE	1847.30	1848.00	1849.00	1850.00	1850.50	1850.60	1850.70	1850.90
	1852.00	1852.60	1853.00	1854.00	1855.00	1856.00		
FLOW	0.00	60.00	260.00	550.00	730.00	770.00	850.00	1020.00
	2760.00	3810.00	4690.00	7170.00	10160.00	13580.00		1130.00

SURFACE AREA=

0. 30. 33. 36. 47. 86.

CAPACITY=

0. 260. 332. 443. 836. 2146.

ELEVATION=

1819. 1845. 1847. 1851. 1860. 1880.

CKEL SPWID CUOM EXPW ELEV COOL CAREA EXPL  
1847.3 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
TOPEL COOD EXPD DAMWID  
1850.5 0.0 0.0 0.

PEAK OUTFLOW IS 6073. AT TIME 42.83 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
6073.	5005.	1845.	940.	270647.
172.	142.	52.	27.	7664.
INCHES	12.25	18.06	18.40	18.40
MM	311.20	458.82	467.46	467.46
AC-FT	2482.	3659.	3728.	3728.
THOUS CU M	3061.	4513.	4598.	4598.

DMF

PEAK OUTFLOW IS 533. AT TIME 44.17 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
533.	465.	160.	81.	23376.
15.	13.	5.	2.	662.
INCHES	1.14	1.56	1.59	1.59
MM	28.93	39.67	40.38	40.38
AC-FT	231.	316.	322.	322.
THOUS CU M	285.	390.	397.	397.

0.1 PMF

PEAK OUTFLOW

OUTFLOW

HYDROGRAPH

## DAM SAFETY INSPECTION

# GALLO DAM

BY WJV

DATE 9-10-79

PROJ. NO. 78-617-233

CHKD. BY DLB

DATE 9-12-79

SHEET NO. D OF P

## Q.2 PMF

0.5 PMF

PEAK OUTFLOW IS 1192. AT TIME 43.17 HOURS

PEAK WAVELENGTH IS 3025. AIR TIME 42.83 HOURS

REFEVOIR

OUTFLOW

HYDROGRAPHS

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
1192.	962.	336.	171.	49235.		
34.	21.	10.	5.	1394.		
	2.36	3.29	3.35	3.45		
INCHES	59.85	83.63	85.04	85.04		
AC-FT	477.	667.	678.	678.		
THOUS CU Y	589.	823.	837.	837.		

CF\$	YEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
3025.	no.	2502.	899.	457.	131476.	
		11.	25.	11.		3/23.
100000		6.12	8.80	8.94		
AC-FT		155.57	223.49	227.08		227.08
100000		1241.	1782.	1811.		1811.
100000		1530.	2198.	2234.		2234.

## HYDROGRAPH ROUTING

MEASURED FROM DAM TO SECTION 2 + 3900 FT DS FROM DAM

[illegible]

# NORMAL DEPTH CHANNEL ROUTING

QU(1)	QU(2)	QU(3)	ELNVT	PLMAX	RINTH	SEL
.0700	.0350	.0700	1820.0	1860.0	3900.	.00100

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC

0.00	1860.00	200.00	1840.00	440.00	1825.00	450.00	1820.00	470.00	1820.00
480.00	1825.00	1000.00	1840.00	1080.00	1860.00				



CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE 9-10-79

PROJ. NO. 78-617-233

CHKD. BY DLB

DATE 9-12-79

SHEET NO. E OF P

Engineers • Geologists • Planners  
Environmental Specialists

STORAGE	0.00	4.56	10.71	22.07	52.23	102.49	172.86	263.33	373.91
	653.57	809.91	971.82	1139.27	1312.28	1490.85	1674.97	1864.65	2059.89
OUTFLOW	0.00	98.99	341.17	796.76	1667.40	3147.46	5408.45	8601.63	12865.59
	25602.55	34681.04	45029.41	56624.15	69451.10	83502.52	98775.26	115269.60	132988.43
STAGE	1820.00	1822.11	1824.21	1826.32	1828.42	1830.53	1832.63	1834.74	1836.84
	1841.05	1843.16	1845.26	1847.37	1849.47	1851.58	1853.68	1855.79	1857.89
FLWD	0.00	98.99	341.17	796.76	1667.40	3147.46	5408.45	8601.63	12865.59
	25602.55	34681.04	45029.41	56624.15	69451.10	83502.52	98775.26	115269.60	132988.43

## HYDROGRAPH ROUTING

ROUTE FROM SECTION 2 TO SECTION 3 \* 6150 FT DS FROM DAM

ISTAQ	ICOMP	IECON	ITAPE	JPL1	JPRT	INAME	ISTAGE	IAUTO
203	1	0	0	0	0	1	0	0
ROUTING DATA								
QROSS	AVG	IRCS	ISAME	IUPT	IPMP		LSTR	
0.0	0.00	1	1	0	0		0	
NSTPS	NSTDL	LAG	AMSK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-1.	0	

## NORMAL DEPTH CHANNEL ROUTING

ON(1)	ON(2)	ON(3)	ELNVT	ELMAX	RLNTH	SEL
0.000	0.000	0.000	1816.0	1840.0	2250.	00100

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC

0.00	1840.00	620.00	1830.00	680.00	1826.00	880.00	1816.00	915.00	1816.00
915.00	1826.00	1240.00	1832.00	1700.00	1840.00				

STORAGE	0.00	2.28	4.57	6.85	9.13	11.42	13.70	15.99	18.30
	44.15	71.80	109.16	156.14	212.89	279.49	355.94	442.23	528.38
OUTFLOW	0.00	58.09	176.59	333.23	517.95	724.47	948.48	1186.80	1440.77
	2400.49	3333.47	4704.31	6586.51	9055.56	12193.85	16071.14	20753.95	26306.05
STAGE	1816.00	1817.26	1818.53	1819.79	1821.05	1822.32	1823.58	1824.84	1826.11
	1828.63	1829.89	1831.16	1832.42	1833.68	1834.95	1836.21	1837.47	1838.74
FLWD	0.00	58.09	176.59	333.23	517.95	724.47	948.48	1186.80	1440.77
	2400.49	3333.47	4704.31	6586.51	9055.56	12193.85	16071.14	20753.95	26306.05

# DAM SAFETY INSPECTION

## GALLO DAM

BY WJV

DATE 9-10-79

PROJ. NO. 78-617-233

CHKD. BY DLB

DATE 9-12-79

SHEET NO. F OF D



**GAI**  
CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists

## HYDROGRAPH ROUTING

ROUTE FROM SECTION 3 TO SECTION 4 @ 11550 FT DS FROM DAM

	ISTAU	ICUMP	TECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
	304	1			0	0	1	0	0
				ROUTING DATA					
		AVG	INES	ISAME	IOPT	IPMP		LSTR	
	0.00	0.00	1	1	0	0		0	
	NSTPS	NSTDUL	LAG	ANSKK	X	TSK	STORA	ISPRAI	
	1	0	0	0.000	0.000	0.000	-1.	0	

NUKMAI, DEPTII CHANNEL KUTING

QN(1)	QN(2)	QN(3)	ELNVT	ELMAX	RLNTH	SEL
.0900	.0400	.0900	1810.0	1840.0	5400.	.00100

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC

0.00	1840.00	260.00	1820.00	400.00	1815.00	410.00	1810.00	430.00	1810.00
440.00	1815.00	900.00	1820.00	1400.00	1840.00				

STORAGE	0.00	4.53	10.30	17.31	39.28	101.51	204.53	341.68	491.32
	823.04	1005.13	1198.03	1401.75	1616.29	1841.65	2077.82	2324.81	2582.62
OUTFLOW	0.00	52.64	177.20	371.12	722.88	1435.52	2702.17	4830.28	7137.48
	15553.21	20456.75	26032.66	32292.07	39248.20	46915.71	55310.16	64447.77	74345.17
STAGE	1810.00	1811.58	1813.16	1814.74	1816.32	1817.89	1819.47	1821.05	1822.63
	1825.79	1827.37	1828.95	1830.53	1832.11	1833.68	1835.26	1836.84	1838.42
FLOW	0.00	52.64	177.20	371.12	722.88	1435.52	2702.17	4830.28	7137.48
	15553.21	20456.75	26032.66	32292.07	39248.20	46915.71	55310.16	64447.77	74345.17

## HYDROGRAPH ROUTING

ROUTE FROM SECTION 4 TO SECTION 5 + 13200 FT DS FROM DAM

ISLAG	ICOMP	JECUM	ITAPE	JPLT	JPRP	INAME	ISTAGE	IAUTO
405	1	0	0	0	0	1	0	0
CRUSS	AVG	IRRS	ISAME	IOPT	IPMP		LSTR	
0.0	0.00	1	1	0	0			
MSIPS	MSIUL	LAG	AMASK	X	ISA	STERR	ISPRAL	
1	0	0	0.000	0.000	0.000	-1	0	

GALLO DAM

78-617-233

G OF P

Engineers • Geologists • Planners  
Environmental Specialists

JSS SECTION	CORORDINATES--SIA, EIRV, SIA, ELEV--LIC		
0-99	1640-99	150-99	1820-99
100-199	1640-99	150-99	1820-99
200-299	1640-99	150-99	1820-99
300-399	1640-99	150-99	1820-99
400-499	1640-99	150-99	1820-99
500-599	1640-99	150-99	1820-99
600-699	1640-99	150-99	1820-99
700-799	1640-99	150-99	1820-99
800-899	1640-99	150-99	1820-99
900-999	1640-99	150-99	1820-99

0.00	1640.00	150.00	1820.00	330.00	1810.00
40.00	1810.00	700.00	1620.00	1000.00	1840.00



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJVDATE 9-10-79PROJ. NO. 78-617-233CHKD. BY DLBDATE 9-12-79SHEET NO. H OF PEngineers • Geologists • Planners  
Environmental Specialists

STORAGE	0.00	2.40	5.56	9.81	21.37	42.45	73.07	113.23	162.92
	281.72	347.46	417.40	491.55	569.91	652.47	739.24	830.22	925.40
OUTFLOW	0.00	68.68	233.94	512.61	1020.44	1867.03	3161.96	4999.55	7465.35
	14985.79	15174.34	25257.26	31432.06	38318.56	45933.04	54292.72	63415.45	73319.46
STAGE	1805.00	1806.84	1808.68	1810.53	1812.37	1814.21	1816.05	1817.89	1819.74
	1823.42	1825.26	1827.11	1828.95	1830.79	1832.63	1834.47	1836.32	1838.16
FLUM	0.00	68.68	233.94	512.61	1020.44	1867.03	3161.96	4999.55	7465.35
	14985.79	15174.34	25257.26	31432.06	38318.56	45933.04	54292.72	63415.45	73319.46

## HYDROGRAPH ROUTING

ROUTE FROM SECTION 6 TO SECTION 7 @ 16400 FT US FROM DAM

ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTU
607	1	0	0	0	0	1	0	0
ROUTING DATA								
QLOSS	CLOSS	AVG	IRCS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
RSTPS NSTOL								
1	0	0	0.000	0.000	X	TSK	STORA	ISPRAT
						0.000	-1.	0

## NORMAL DEPTH CHANNEL ROUTING

Q(1) Q(2) Q(3) ELN(1) ELN(2) ELN(3) SEL  
0.0700 0.0400 0.0700 1804.0 1840.0 800. 00100

CROSS SECTION COORDINATES--STA,ELEV,STA,ELEV--ETC  
0.00 1840.00 180.00 1820.00 320.00 1814.00 320.00 1804.00 380.00 1804.00  
380.00 1814.00 800.00 1820.00 1100.00 1840.00

STORAGE	0.00	2.09	4.18	6.26	8.35	10.44	14.13	23.74	39.50
	83.96	108.79	135.20	163.19	192.76	223.92	256.66	290.98	326.88
OUTFLOW	0.00	196.85	601.36	1139.79	1778.59	2496.61	3399.06	4799.21	6987.73
	15011.82	20620.67	27209.91	34780.35	43341.30	52907.20	63495.83	75127.13	87822.54
STAGE	1804.00	1805.89	1807.79	1809.68	1811.58	1813.47	1815.37	1817.26	1819.16
	1822.95	1824.84	1826.74	1828.63	1830.53	1832.42	1834.32	1836.21	1838.11
FLUM	0.00	196.85	601.36	1139.79	1778.59	2496.61	3399.06	4799.21	6987.73
	15011.82	20620.67	27209.91	34780.35	43341.30	52907.20	63495.83	75127.13	87822.54

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJVDATE 9-10-79PROJ. NO. 78-617-233CHKD. BY DLBDATE 9-12-79SHEET NO. I OF PEngineers • Geologists • Planners  
Environmental Specialists

## HYDROGRAPH ROUTING

ROUTE FROM SECTION 7 TO SECTION 8 @ 21050 FT DS FROM DAM

ISTAU	ICUMF	ILCON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
708	1	0	0	0	0	1	0	0
ROUTING DATA								
GLSS	CLSS	AVG	INRES	ISAME	IOPT	IPMP	LSIR	
0.0	0.000	0.00	1	1	0	0	0	
WSIES	WSIUE	LAG	ARSKK	A	ISK	SIUKA	ISPKAT	
1	0	0	0.000	0.000	0.000	-1.	0	

## NORMAL DEPTH CHANNEL ROUTING

UN(1)	UN(2)	UN(3)	ELAVT	ELMAX	RLWTH	SEL
0.000	0.000	0.000	1798.0	1840.0	4650.	00100

## CROSS SECTION COORDINATES--STA, ELEV, STAGE, ELEV--ETC

	0.00	1840.00	300.00	1820.00	670.00	1808.00	670.00	1798.00	735.00	1798.00
STORAGE	0.00	15.34	30.68	46.01	61.35	79.82	122.10	191.99	289.48	
	507.25	742.43	935.87	1147.56	1377.51	1625.71	1892.17	2176.89	2479.87	
OUTFLOW	0.00	274.88	837.51	1583.57	2465.81	3521.39	4962.57	6963.75	9691.04	
	17899.04	23852.57	30922.42	39157.16	48608.31	59328.64	71371.34	84789.48	99635.82	
STAGE	1798.00	1800.21	1802.42	1804.63	1806.84	1809.05	1811.26	1813.47	1815.68	
	1820.11	1822.32	1824.53	1826.74	1828.95	1831.16	1833.37	1835.58	1837.79	
FLUD	0.00	274.88	837.51	1583.57	2465.81	3521.39	4962.57	6963.75	9691.04	
	17899.04	23852.57	30922.42	39157.16	48608.31	59328.64	71371.34	84789.48	99635.82	

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233CHKD. BY DLB

DATE

9-12-79

SHEET NO.

J

OF

PEngineers • Geologists • Planners  
Environmental Specialists

## SUMMARY OF DAM SAFETY ANALYSIS

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	ELEVATION		INITIAL VALUE	SPILLWAY CHEST		TUP OF DAM	TIME OF MAX OUTFLOW HOURS	DURATION OVER TUP HOURS	TIME OF FAILURE HOURS
		STORAGE	OUTFLOW	1847.30	1847.30	1850.50				
.10	1849.94	0.00	0.00	332.	332.	443.	0.00	44.17	0.00	0.00
.20	1851.05	.55	463.	0.	0.	730.	5.33	43.17	0.00	0.00
.30	1851.45	.95	478.				1192.	42.83	0.00	0.00
.40	1851.80	1.30	491.				1815.	42.83	0.00	0.00
.50	1852.15	1.65	504.				2420.	42.83	0.00	0.00
1.00	1853.56	3.06	558.				3025.	42.83	0.00	0.00
							6073.	42.83	0.00	0.00

SECTION @ 3900 FT  
DS FROM DAM

## PLAN 1 STATION 102

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	530.	1825.1	44.50
.20	1167.	1827.2	43.67
.30	1784.	1828.6	43.33
.40	2383.	1829.4	43.33
.50	2979.	1830.3	43.33
1.00	5998.	1833.0	43.17

SECTION @ 6150 FT  
DS FROM DAM  
(@ 1<sup>ST</sup> BRIDGE CROSSING)

## PLAN 1 STATION 203

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	530.	1821.1	44.67
.20	1165.	1824.7	43.83
.30	1773.	1827.3	43.67
.40	2356.	1828.5	43.83
.50	2946.	1829.4	43.83
1.00	5948.	1832.0	43.50



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJVDATE 9-10-79PROJ. NO. 78-617-233CHKD. BY DLBDATE 9-12-79SHEET NO. K OF PEngineers • Geologists • Planners  
Environmental Specialists

## PLAN 1 STATION 304

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	515.	1815.4	45.33
.20	1079.	1817.1	44.83
.30	1656.	1818.2	44.67
.40	2218.	1818.9	44.83
.50	2786.	1819.5	44.67
1.00	5742.	1821.5	44.33

SECTION @ 11550 FT  
DS FROM DAM

## PLAN 1 STATION 405

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	515.	1813.6	45.50
.20	1078.	1815.9	45.00
.30	1656.	1817.6	44.83
.40	2218.	1819.0	44.83
.50	2785.	1820.2	44.83
1.00	5731.	1823.8	44.50

SECTION @ 13200 FT  
DS FROM DAM(@ COAL OPERATIONS  
STRUCTURES)

## PLAN 1 STATION 506

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	514.	1810.5	45.67
.20	1072.	1812.5	45.33
.30	1646.	1813.7	45.17
.40	2207.	1814.7	45.17
.50	2769.	1815.5	45.17
1.00	5705.	1818.4	44.67

SECTION @ 15600 FT  
DS FROM DAM  
(@ 1ST RESIDENCE)

## PLAN 1 STATION 607

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	514.	1807.4	45.83
.20	1072.	1809.4	45.33
.30	1646.	1811.2	45.17
.40	2207.	1812.7	45.17
.50	2769.	1814.0	45.17
1.00	5702.	1818.0	44.83

SECTION @ 16400 FT  
DS FROM DAM  
(@ 2ND BRIDGE CROSSING)

## PLAN 1 STATION 708

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.10	511.	1801.1	46.17
.20	1068.	1803.1	45.67
.30	1641.	1804.8	45.33
.40	2201.	1806.2	45.33
.50	2761.	1807.5	45.33
1.00	5628.	1812.0	45.33

SECTION @ 21050 FT  
DS FROM DAM  
(@ 3RD BRIDGE CROSSING  
(@ 2ND GROUP OF RESIDENCE)

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLR

DATE

9-12-79

SHEET NO.

L

OF

P



Engineers • Geologists • Planners  
Environmental Specialists

BREACHING ANALYSIS  
CONSISTS OF SAME INPUT  
DATA AS FOR THE  
OVERTOPPING ANALYSIS  
W/ THE ADDITION OF  
THE BREACH  
DATA GIVEN  
HERE

BREACHING

DAM SAFETY INSPECTION  
GALLO DAM \*\*\*\*\* BREACHING  
10-MINUTE TIME STEP AND 48-HOUR STORM DURATION

JOB SPECIFICATION									
Q2	Q3	Q4	Q5	Q6	Q7	Q8	Q9	Q10	Q11
284	0	10	0	0	0	0	0	0	0

MULTI-PLAN ANALYSIS TO BE PERFORMED  
NPLAN= 5 NRIID= 1 NRTIO= 1

NRIID= .15

## HYDROGRAPH ROUTING

ROUTE THROUGH RESERVOIR

PLAN

DAM DATA			
TOTEL	CUD	EXP	DAMWID
1850.5	0.0	0.0	0.0

DAM BREACH DATA			
BRWID	Z	ELW	TRAIL
0.0	.50	1821.50	.50
			1847.50
			1850.50

STATION	
101	PLAN 1, RATIO 1

REGIO DAM FAILURE AT 42.0/ HOURS  
PEAK OUTFLOW IS 2100. AT TIME 43.17 HOURS

DAM BREACH DATA			
BRWID	Z	ELW	TRAIL
350.	3.00	1821.50	.50
			1847.50
			1850.50

STATION	
101	PLAN 2, RATIO 1

REGIO DAM FAILURE AT 42.0/ HOURS  
PEAK OUTFLOW IS 2000. AT TIME 42.90 HOURS

SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

M

OF

P

Engineers • Geologists • Planners  
Environmental Specialists

PLAN

③

DAM BREACH DATA  
Z ELUM TFAIL WSEL FAILED  
.50 1821.50 4.00 1847.30 1850.50  
STATION 101, PLAN 3, RATIO 1

BRWID  
0.

BEGIN DAM FAILURE AT 42.67 HOURS

PEAK OUTFLOW IS 2538. AT TIME 46.67 HOURS

④

DAM BREACH DATA  
Z ELUM TFAIL WSEL FAILED  
3.00 1821.50 4.00 1847.30 1850.50  
STATION 101, PLAN 4, RATIO 1

BRWID  
350.

BEGIN DAM FAILURE AT 42.67 HOURS

PEAK OUTFLOW IS 3002. AT TIME 43.50 HOURS

⑤

DAM BREACH DATA  
Z ELUM TFAIL WSEL FAILED  
1.00 1821.50 2.00 1847.30 1850.50  
STATION 101, PLAN 5, RATIO 1

BRWID  
100.

BEGIN DAM FAILURE AT 42.67 HOURS

PEAK OUTFLOW IS 5723. AT TIME 43.54 HOURS



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

N OF P



CONSULTANTS, INC.

Engineers • Geologists • Planners  
Environmental Specialists

THE DAM BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .042 HOURS DURING BREACH FORMATION. DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOURS. THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH. INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

TIME (HOURS)	TIME FROM BEGINNING OF BREACH (HOURS)	INTERPOLATED BREACH HYDROGRAPH (CFS)	COMPUTED BREACH HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (CFS)	ACCUMULATED ERROR (AC-FI)
42.667	0.000	737.	737.	0.	0.	0.
42.708	.042	1005.	895.	110.	110.	0.
42.750	.083	1273.	1157.	116.	226.	1.
42.792	.125	1540.	1470.	71.	296.	1.
42.833	.167	1808.	1808.	0.	296.	1.
42.875	.208	2146.	2155.	-10.	287.	1.
42.917	.250	2483.	2499.	-16.	271.	1.
42.958	.292	2821.	2831.	-10.	260.	1.
43.000	.333	3158.	3158.	0.	260.	1.
43.042	.375	3432.	3464.	-32.	229.	1.
43.083	.417	3706.	3744.	-39.	190.	1.
43.125	.458	3979.	3999.	-19.	171.	1.
43.167	.500	4253.	4253.	0.	171.	1.
43.208	.542	4463.	4479.	-16.	154.	1.
43.250	.583	4672.	4682.	-10.	145.	0.
43.292	.625	4882.	4895.	-13.	132.	0.
43.333	.667	5092.	5092.	0.	132.	0.
43.375	.708	5230.	5278.	-48.	83.	0.
43.417	.750	5368.	5431.	-63.	21.	0.
43.458	.792	5506.	5552.	-46.	-25.	0.
43.500	.833	5644.	5644.	0.	-25.	0.
43.542	.875	5645.	5703.	-59.	-84.	0.
43.583	.917	5645.	5723.	-77.	-161.	0.
43.625	.958	5646.	5704.	-57.	-219.	1.
43.667	1.000	5647.	5647.	0.	-219.	1.
43.708	1.042	5516.	5556.	-40.	-260.	1.
43.750	1.083	5372.	5432.	-60.	-320.	1.
43.792	1.125	5234.	5278.	-44.	-369.	1.
43.833	1.167	5096.	5096.	0.	-369.	1.
43.875	1.208	4863.	4890.	-28.	-397.	1.
43.917	1.250	4629.	4664.	-35.	-431.	1.
43.958	1.292	4396.	4420.	-24.	-456.	2.
44.000	1.333	4162.	4162.	0.	-456.	2.
44.042	1.375	3889.	3894.	-5.	-461.	2.
44.083	1.417	3616.	3620.	-4.	-466.	2.
44.125	1.458	3343.	3344.	-1.	-467.	2.
44.167	1.500	3069.	3069.	0.	-467.	2.
44.208	1.542	2817.	2800.	17.	-450.	2.
44.250	1.583	2564.	2539.	25.	-426.	1.
44.292	1.625	2312.	2291.	20.	-406.	1.
44.333	1.667	2059.	2059.	0.	-406.	1.
44.375	1.708	1876.	1845.	31.	-375.	1.
44.417	1.750	1692.	1650.	42.	-334.	1.
44.458	1.792	1509.	1477.	32.	-300.	1.
44.500	1.833	1326.	1326.	0.	-300.	1.
44.542	1.875	1124.	1196.	-72.	-272.	1.
44.583	1.917	1122.	1086.	36.	-240.	1.
44.625	1.958	1020.	994.	26.	-210.	1.
44.667	2.000	918.	918.	0.	-210.	1.

(5)

# DAM SAFETY INSPECTION

## GALLO DAM

BY WJV

DATE 9-10-79

PROJ. NO. 78-617-233

CHKD. BY DLB


DATE 9-12-79

SHEET NO. 0 OF D

**יובל**  
CONSULTANTS

CONSULTANTS, IN

Engineers • Geologists • Planners  
Environmental Specialists



SUBJECT

DAM SAFETY INSPECTION

GALLO DAM

BY WJV

DATE

9-10-79

PROJ. NO.

78-617-233

CHKD. BY DLB

DATE

9-12-79

SHEET NO.

P OF P

Engineers • Geologists • Planners  
Environmental Specialists

## SUMMARY OF DAM SAFETY ANALYSIS

PLAN	RATIO OF PWF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	TOP OF DAM ELEVATION
1	.15	1850.55	.05	445.	5168.	.38	43.17	42.67	1850.50
2	.15	1850.52	.02	443.	20085.	.18	42.90	42.67	443.
3	.15	1850.66	.16	449.	2538.	1.42	46.67	42.67	730.
4	.15	1850.52	.02	443.	3662.	.25	43.50	42.67	
5	.15	1850.53	.03	444.	5723.	.25	43.58	42.67	

## STATION S06

PLAN	RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1	.15	2279.	1814.8	45.33
2	.15	3076.	1815.9	44.33
3	.15	1901.	1814.3	48.00
4	.15	2448.	1815.0	45.50
5	.15	2943.	1815.7	45.17

SECTION @ 15600 FT  
DS FROM DAM  
(@ 1<sup>st</sup> RESIDENCE)

## STATION 708

PLAN	RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1	.15	2250.	1806.3	45.67
2	.15	2985.	1807.9	44.67
3	.15	1863.	1805.3	48.00
4	.15	2423.	1806.7	45.83
5	.15	2670.	1807.7	45.50

SECTION @ 21050 FT  
DS FROM DAM  
(@ 2ND GROUP OF RESIDENCES)



12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.

APPENDIX D  
PHOTOGRAPHS

PHOTOGRAPH 1

View of reservoir and surrounding hillsides as seen from the spillway channel.

PHOTOGRAPH 2

View of the downstream face of the dam. Note the siphon line and gate valve in the right center portion of the photo, and the lush vegetation on the D/S slopes.

PHOTOGRAPH 3

View of the spillway from near the plunge pool. Note concrete caps that were added to the weir crest and left sidewall (also to the right sidewall). Also note the cracking of the weir, and the apparent rotation of the weir cap.


PHOTOGRAPH 4

View of the downstream area as seen from the spillway crest. Note that a portion of the downstream terminus of the spillway has spalled off. Some minor cracking and efflorescence is visible on the spillway sidewalls.





1



3



2



4

MURRAY, DEPTID

URCE  
"0900

CRUS

44

STORAGE

OUTFLOW

SLAGE

FLOW

PHOTOGRAPH 5

View of an erosion ditch at the downstream edge of the dam crest.

PHOTOGRAPH 6

View of a spring downstream of the dam at the left abutment.

PHOTOGRAPH 7

View of a small spring that flows along the downstream toe of the dam.

PHOTOGRAPH 8

View of the toe of the dam near the discharge end of the low level outlet. Note the heavy vegetation on the downstream face of the dam.

MINIMAL

STORA

OUTFL

STAC

PL

MINIMAL



6



8



5



7

STORAGE

OUTFLOW

STAGE

FLOW

MORAL DEP

STORAGE

OUTFLOW

STAGE

FLOW



NORMAL DEPT

000  
.00

000

STORAGE

QUIP

STAGE

FLW

APPENDIX E  
GEOLOGY


## GEOLOGY

Gallo Dam is located in the Allegheny Mountain Section of the Appalachian Plateaus Physiographic Province. The Allegheny Mountain Section is characterized by gently folded sedimentary rock strata of Pennsylvanian age or older. Major structural axes strike from southwest to northeast of flanking strata dipping northwest and southeast.

Gallo Dam and reservoir are located just southwest of Jennerstown at the base of the east flank of Laurel Hill. Structurally the dam lies just west of the axial trace of the Johnstown syncline. Bedrock beneath the dam, therefore, gently tips to the southeast at approximately 1 to 2 degrees.

The dam and reservoir are located on sedimentary rock strata of the Conemaugh Group of Pennsylvanian age. The embankment is constructed on bedrock of the middle members of the Conemaugh Group. This section typically consists of interbedded shales and siltstones some sandstone, and a few thin limestones and minor coal beds.

(@ 2ND GROUP OF RESIDENTS)





10-419  
GALLU  
HAM SA

288  
40

REI

RODIE

PLAN

①

②

APPENDIX F  
FIGURES

PLAN

③

④

⑤

LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	General Plan (field inspection notes)
2	Layout of Dam
3	Embankment Sections
4	Spillway Detail





FIGURE 1 - GALLO DAM  
GENERAL PLAN  
FIELD INSPECTION NOTES










FIGURE 2









FIGURE 3

31







FIGURE 4



APPENDIX G

REGIONAL VICINITY AND WATERSHED BOUNDARY MAP



----- LONGEST WATERCOURSE  
○ CENTROID OF DRAINAGE AREA

**LIGONIER, PA.**

N4007.5—W7907.5/7.5


1967  
PHOTOREVISED 1973  
AMS 5164 II NW—SERIES V831

**REGIONAL VICINITY AND**




CONTOUR INTERVAL IS MEAN

LONGEST WATERCOURSE  
CENTROID OF DRAINAGE AREA



REGIONAL VICINITY AND WATERSHED BOUNDARY MAP



CONTOUR INTERVAL 20 FEET  
DATUM IS MEAN SEA LEVEL

BOSWELL, PA.

N4007.5—W7900/7.5

1967  
PHOTOREVISED 1973  
AMS 5164 II NE—SERIES V831